

## 1966 Catalina 2+2

Posted by studelover - 2016/03/02 19:15

---

I am working on my 1966 2+2 Pontiac, I just installed the front Bumpers and one side the wrap around edge is sticking out. Do I have a bumper problem or a bracket problem? There are 3 holes on the bumper edge I have bumper bolts going through 2 of the holes am I missing something there.

[http://www.pontiac2plus2registry.com/images/fbfiles/images/66revisited\\_2016\\_03\\_02\\_007.JPG](http://www.pontiac2plus2registry.com/images/fbfiles/images/66revisited_2016_03_02_007.JPG) Rodney

=====

## Re:1966 Catalina 2+2

Posted by studelover - 2016/03/04 20:13

---

There is a bracket that is not in the manual. It fits on the third bumper bolt. I have a 1966 Catalina in a junk yard near me. It has those brackets on the car, I got them yesterday before the snow.